

## Massachusetts Department of Environmental Protection Bureau of Resource Protection – Watershed Permitting Program

Sanitary Sewer Overflow (SSO)/Bypass Notification Form FOR DEP USE ONLY

Tax Identification Number

### A. Reporting Facility

important: When filling out forms on the computer, use only the tab key to move your cursor - do not use the return key.





See DEP Regional Office telephone and fax numbers at the end of this form.

NOTIFICATION TO
ALL AT
S:40pm 3/15/16

1.	Facility Information			1		
	HULL MA W	PCF		140101231		
	Reporting Sewer Authority			Permit #		
2.	Authorized Representative Train	nsmitting Form:				
	ARAM First Name	VARJAGED	181-9	25-0906		
	A 1 -	Last Name	Telephone	No.		
	PROJECT MANA	iger a	verphedian @ woo	odard curren, con		
B	. Phone Notifications:					
	· · · · · · · · · · · · · · · · · · ·	TA - 2 2				
1.	MassDEP staff contacted:	DAVID BURN	last name			
	Data/Time contested:	3/15/16	11:46			
	Date/Time contacted:	Date	Time	am pm		
2.	EPA staff contacted:	DAVID first name	TURIN last name			
	D. 1. 67	2/15/16	11148			
	Date/Time EPA contacted:	Date	Time	am pm		
3.	Board of Health contacted:	Joyce First Name	SULLIVA	~		
		3/15/16	Last Name			
	Date/Time contacted:	Date	Time	— am pm		
4.	Others notified (select all that a	thers notified (select all that apply);   Conservation Commission				
	☐ Harbormaster ☐ Shellfish Warden ☐ Division of Marine Fisheries					
	☐ Downstream Drinking Water	Downstream Drinking Water Supplier Watershed Association  RYAN Joyce 3/15/16 11:58 AM				
	☐ Beach Resource Manager	Other	specify)	11:58 AM		
C.	SSO Information		opocity)			
		3/15/16	10:15			
1.	SSO Discovered:	Date	Time	am pm		
	By: BILL BOORNA	ZIAN + ERICS	Ton (woodard+C	urran)		
2.	SSO Stopped:	3/15/11	6 10:16 Time	— ⊠am □pm		
3.	SSO Discharge from: Sanitary Sewer Manhole Pump Station					
	☐ Backup into Property ☑	Other	gare Box AT P	ump STAT 3.		
	100	Other:	specify) on 14"	FORCE MAIN		
4.	Backup into Property Other:    Ground Surface (no release to surface water)   Ground Surface (no release to surface wat					
	☐ Direct to Receiving Water	ī	surface water)			
	☐ Catch basin to Receiving W	ater 7	surface water)			
	☐ Backup into Property Basen					



# Massachusetts Department of Environmental Protection Bureau of Resource Protection – Watershed Permitting Program Sanitary Sewer Overflow (SSO)/Bypass Notification Form

FOR DEP USE ONLY

Tax Identification Number

C.	SSO Information (cont.)			
5.	Location: Pump Station 3 13 Rockland Circle, Hull, MA  (Description of discharge site of closest address)  Estimated SSO Volume at time of this Report:  Method of Estimating Volume:  Visual/calculated > VALVE BOX  of albeited ground area  RISER,			
6.	Cause of SSO Event:			
	☐ Rain Event ☐ Pump Station Failure ☐ Insufficient Capacity in System			
	☐ Treatment Unit failure			
7.	Sewer System Blockage: Pipe Collapse Root Intrusion Grease Blockage  VALVE Exercising for The FORCE MAIN  (Specify) WAS STUCK OPEN. SUSPECT FAILURE OF  Corrective Actions Taken: PACKING OF PACKING GLOND SIDE CONTRACTOR  WAS ASLE TO STOP THE LEAK BY CLOSING			
	the VALVE ACTUATOR. WE SUSPECT HAT THE			
	VALVE 13/was unworkable.			
	Impact Area cleaned and/or disinfected:   Yes  No  APPLIED LIME (CaO) to area around the gate box.  GATE Box (Inguid contained in) was vaccounted out.  Corrective Actions Completed:  Yes  No			
D.	Comments/Attachments/Follow-up  I wish to provide (select all that apply):  Attachment Additional comments below:  No additional comments or attachments  Additional comments and planned actions:  See attachments + ADDITIONAL Comments / PICTURES			



### Massachusetts Department of Environmental Protection Bureau of Resource Protection - Watershed Permitting Program

FOR DEP USE ONLY

### Sanitary Sewer Overflow (SSO)/Bypass **Notification Form**

Tax Identification Number

### E. Certification Statement

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

Signature of Authorized Representative

3-19-16 Date Signed

Please keep a copy of this report for your records. When submitting additional information, include the MassDEP Incident Number from this report.

### MassDEP Regional Office and EPA Telephone and Fax Numbers:

Northeast Region

Phone: 978-694-3215

Fax: 978-694-3499

Southeast Region

Phone: 508-946-2750

Fax: 508-947-6557

Central Region

Phone: 508-792-7650

Fax: 508-792-7621

Western Region

Phone: 413-784-1100

Fax: 413-784-1149

**EPA Contact** 

Phone: 617-918-1870

Fax: 617-918-0870

DEP 24-hour

Phone: 888-304-1133 emergency

### S.S.O. DATE: MARCH 15, 2016

### SUMMARY OF ADDITIONAL INFORMATION RELATED TO S.S.O. TO INCLUDE CMOM/AOC REQUIRED INFO

- A. Asset from which the unauthorized discharge occurred: 14-inch force main isolation valve.
- B. Location: 13 Rockland Circle, Hull, MA.

LAT / LON:

42 degr 15'55.81" / -70 degr 51'21.22"

- C. Cause of unauthorized discharge: SSO form Section C-6uspected cause mechanical failure of 14-inch buried gate valve
- D. Unauthorized discharge not caused by blockage
- E. Last inspection date/maintenance/repair of ailed asset: Unknown
- F. Date/Time unauthorized discharge began: SSO form section C-1
- G. Date/Time unauthorized discharge stopped: SSO form section C-2
- H. Source of Notification: field crew SSO form section C-1
- Estimated gallons of wastewater released: SSO section C-5. 2 gallons to ground surface, and 8 gallons sub-surface in gate box riser.
- J. Method of calculation of wastewater released: SSO section C-5. Visual to surface; calculated riser volume and volume that was vacuumed up/out.
- K. Details of the release: The unauthorized discharge did not reach any storm water catch basins, or any portion of the Town's MS4. No storm water catch basins in this area. Nearest down-gradient receiving water is Hull-Hingham Bay. See attached pictures.
- L. Details of the release: The unauthorized discharge did not reach any wetland or surface water.
- M. Measures taken to minimize volume of release and duration: SSO section C-7. Valve exercise operation immediately halted when wastewater observed coming to surface. Valve operator immediately closed valve to stop the discharge.
- N. Measures taken to clean area: SSO form section C-7. Gate box riser was vacuumed/cleaned out by sub-contractor. Lime was applied to the grassy area around gate box.
- O. Corrective actions taken: SSO section C-7. Valve is not operable at the present time. Valve cannot be operated until further notice. Caution tape and tag to be applied to alert staff that valve cannot be used. Long-term corrective action valve will need to be replaced.
- P. Date of last unauthorized discharge in same general location: Unknown.

### Aram Varjabedian

From:

Aram Variabedian

Sent:

Tuesday, March 15, 2016 5:40 PM

To:

'Turin, David'; Burns, David (DEP); 'Joyce, Ryan (FWE)'; 'jsullivan@town.hull.ma.us'

Cc:

Dow, James; Frank Cavaleri; Kevin Stetson; Bill Boornazian

Subject:

SSO at Hull Pump Station #3 - Hull WPCF - MA0101231

### Good afternoon:

This email is to summarize the SSO incident that took place this morning at the #3 Pump station in Hull, MA at 13 Rockland Circle. Phone calls and messages were left this morning, informing you of the incident. The SSO form will be completed and forwarded in the next day or two.

At approximately 10:15am, work was proceeding at this location to attempt to exercise a buried gate valve which is on the force main discharge from the pump station. The valve was not operable and the work was co-ordinated with Hydra-Tech of Sterling, MA with the goal to get the valve operable so that the valve could be closed for various maintenance work planned inside of the pump station.

Please see Bill Boornazian's comments below:

At 10:15am the valve box for the isolation valve on the pump station 3 force main slowly filled with wastewater and approximately 2 gallons spilled up and over the valve box onto the grass. The cause was likely due to failure of the packing around the stem of the gate valve. The valve was being exercised for approximately 1 hour prior to the leak being detected.. At that time, the valve was believed to be a few turns from being closed when it was backed off about 10 turns, and then the torque dropped out and the leaking occurred. The valve operator started again closing the valve stem which stopped the leak by likely pushing the packing back down. At this time, the valve is not leaking under full operating pressure, and the valve is believed to be unworkable. Based on the pump flow rate observed, the valve is believed to be stuck in the open position.

All excess wastewater in the valve box was vacuumed out before we left the station.

We are monitoring the station operation for proper operation and will inspect the gate box daily over the next several days. The SSO form will include some additional information. We estimate that approximately 2 gallons of wastewater spilled onto the ground, and some additional wastewater [unknown quantity] leaked into the gate box, and this was vacuumed up.

Should you have any questions, please don't hesitate to contact me.

Sincerely,

#### Aram

Aram Varjabedian
Plant Manager
Hull Wastewater Treatment Facility
1111 Nantasket Avenue |Hull, MA 02045
Phone 781.925.0906 | Fax 781.925.3056 | Cell 339.214.8334
www.woodardcurran.com







### **Hull Wastewater**

### **Work Order Information**

Date:

03/18/2016

Type:

**Corrective Maintenance** 

Status: Completed

Asset:

PS 3

Priority: Normal

Reason: Client Support

### **Description of Issue**

Description: PS 3 SSO GPS and catch basins survey

Notes:

Survey of latitude, longitude of recent SSO along with pictures of site

### **Actions Taken**

Staff:


**Eric Sutton** 

Service:

Used GXBlue to grab latitude, and longitude of the SSO on 3/15 /16 along with pictures of site at station 3

### **Photos**







Picture looking left from driveway no catch basins anywhere on street. There a small lagoon on right 150 to 200 yards on right

This work order was created in doFORMS.













from station to

MARSH

(Botton picture)

(top picture)
que box in grassy
quea just infront
of station building

box (bottom)
. time applied to
Surface (Top
picture)

1 GPS co-ordinates (bottom)

(Top picture)
Rockland Circle ROMANY
NO CATEHBASINS

